

Hardware : 5300 / 6300 : Beeper Volume Adjustment

Follett Technical Support Knowledgebase Article

Applies to:

5300 / 6300 | Zebex Models: 3190 & 3190BT





Symptoms:

A customer may want to lower the volume of the beeps emitting from the handheld scanner.

Solution:



Start Of Configuration

Barcode Value	Barcode Label	Description
GR02		Low beeper tone
GR01		Medium beeper tone
GR03		High beeper tone
GR05		Speaker disable



End Of Configuration